Product Name: Hydropel



Description: A game-changer in windshield protection. Designed for ease without compromising performance, Hydropel utilizes advanced nano-technology for unmatched durability against wiper blade abrasion. Its super hydrophobic formula ensures rain slides off effortlessly, providing exceptional optical clarity and enhanced safety, even in low-light conditions.

Coverage: Hydropel is particularly suitable for all glass surfaces and specifically for front and rear windscreen where there is abrasion from wipers.

Technical Data		General Data	
Product	Hydropel	**Category**	Retail After Care
Flash Point	100°C	**Coverage**	$1m^2$ - $1.5m^2$
Appearance	Colorless		
Physical State	Liquid		
Odour	Mild Solvent	**Features:**	
Specified Gravity	0.98 g/cm³	✓	Simple Application
Hazard	Non-Hazardous	✓	Superior Protection and Performance
Application	Detailing/Protection	✓	Excellence Durability
Storage	5-35°C/41-95°F	✓	Exceptional Vision Clarity
		✓	Wiper Abrasion Resistant

Directions: 1.Ensure the vehicle's windshield is clean and dry before application.

2. Place Hydropel on the windshield. Press the button with both thumbs applying even pressure until you hear 2 distinct popping sounds. This indicates the inner tubes have opened and the coatings have released onto the bottom felt pad.

Web
www.auto-triz.com

Email
info@auto-triz.com

3. Apply the coated felt pad directly onto the glass surface. Use horizontal strokes to spread the glass coating solutions evenly across the windshield. Repeat this process several times, performing approximately 2 passes from left to right each time, to ensure thorough penetration of the coating into the glass surface.

4. As you apply the coating, you'll observe the surface haze up initially, gradually diminishing with each subsequent pass, go through it with few more passes until the haze is reduced significantly.

5. Use a lint-free microfiber cloth to wipe off any excess coating haze using circular or polishing motions until the surface is completely clear. For low humidity climate and temperature below 10°C, wipe after 15-30 minutes.



Precaution: Ensure the substrate is free from contaminants prior to and during the application process**.** Keep coating away from all polish and compound dust during the curing process.

Curing: 1. Keep the windshield away from water for 12 hours after application.

2. Refrain from washing or using the wiper for 24 hours to achieve maximum results.

Web
www.auto-triz.com

Email
info@auto-triz.com